

Bevertalstraße 20 D-42499 Hückeswagen Tel.: +49 2192 9166 0 Fax: +49 2192 9166 66

Mounting

- Drill a hole with Ø 12 mm for the connection cable
- Insert the connection cable through the hole
- Adjust the pole mount socket and press it against the pole
- Fasten the pole mount socket to the pole with the two drilling screws (4,8 x 22; SAF8)

Installation Instructions

Pole mount socket HSW 4015

Intended use

The pole mount socket HSW 4015 is intended to add-on to a suitable lighting poles.

Any other use of this product requires the consultation with the manufacturer.

Safety instructions

When working on electrical systems, the valid regulations such as VDE 0100 must be observed. Installation may only be carried out by qualified personnel or instructed persons in a de-energized state.

Service


In the event of malfunctions or complaints regarding the product, please contact your sales representative or the manufacturer.


Technical data

Socket	CEE-outlet
	IP44
Nominal voltage / -current	250 V / 16 A
Measurements (L x W x H)	111 x 86 x 93 mm

Connection

 Insert the connecting cable into the cable fuse box and connect according to the cable assignment





drill pattern
Not to scale!